

Software Update Notification

You need a Windows-compatible computer and a pin to pin RS-232 cable or USB cable.

UPDATE RECOMMENDED FOR ALL DUAL DSP UNITS

PRESS: MENU/STATUS/VERSION INFO

- IF THE FIRMWARE IS 1.9.9 OR ABOVE IT IS SAFE TO LOAD THIS CODE
- IF YOU HAVE JUST INSTALLED A DUAL DSP IT IS SAFE TO LOAD THIS CODE
- IF YOU HAVE NOT JUST INSTALLED A DUAL DSP & THE FIRMWARE IS 1.0.3 OR BELOW DO **NOT** LOAD THIS CODE

Release Notes: The software update will provide functionality/usability improvements to the features and capabilities of this model. These are as follows:

Corrects potential for CD truncation

Corrects audio stuttering with Kaliedescape BD players

Addresses potential for false trigger standby command on power up

Addresses potential for distortion on PEQ

THIS IS A DSP UPDATE THAT REQUIRES AT LEAST 2 POWER CYCLES

FOLLOW THE INSTRUCTIONS ON THE TOUCHSCREEN

IF THE TOUCHSCREEN DISPLAYS "Updating DSP Software" BUT THE PROGRESS BAR DOES NOT ADVANCE, SIMPLY CYCLE POWER TO RESTART THE DSP UPDATE

