

Software Update Notification

You will need a Windows-compatible computer and a (pin to pin) RS-232 cable.

☒ RECOMMEND UPDATING ALL UNITS.

☐ UPDATE UNITS S/N: _____
PLEASE ADVISE CUSTOMERS AND UPDATE UNITS ONLY WHERE APPLICABLE.

☐ NEW FEATURES ADDED IN THIS SOFTWARE RELEASE ARE INTENDED TO IMPROVE OPERATION/PERFORMANCE. UPDATE IS OPTIONAL.

Dependencies and requirements for this software update (this info is accessible through pressing: MENU-STATUS->VERSION INFO):

Kickstart 1.1.5

Release Notes: The software update will provide functionality/ usability improvements to the features and capabilities of this model. These are as follows:

- Added support to input selection. Input selection is now much faster.
- Added new "Profiles" feature.
- Added new "LCD timeout option: screensaver or main video source"
- Added 1-second option to the Temporary Display durations.
- New feature "programmable mute" with 3 options: classic, specific & dampening.
- New feature "volume level at startup" with 2 options: last and specific with mute.
- Standby and mute commands disabled when auto calibration is being performed.
- Rotary default settings have been updated to improve volume responsiveness.
- Added new "Titan Updater" feature to enable the user to update the DSP chip via RS-232 cable, when applicable.
- Improved support to mute state when changing inputs in order avoid potential volume spikes.
- Added support for PAL region 2 dvd.
- Added support for rapid volume adjustments.
- Implemented Dialog Normalization Flags.
- Added ASA default to APART when only one back speaker is available.