

CLASSE

Date: February 24, 2011

Model: SSP-800

Software Update Number: v3.0.1

Software Update Notification

You will need a Windows-compatible computer and a (pin to pin) RS-232 cable.

RECOMMEND UPDATING ALL UNITS.

UPDATE UNITS S/N: _____
PLEASE ADVISE CUSTOMERS AND UPDATE UNITS ONLY WHERE APPLICABLE.

NEW FEATURES ADDED IN THIS SOFTWARE RELEASE ARE INTENDED TO IMPROVE OPERATION/PERFORMANCE. UPDATE IS OPTIONAL.

Dependencies and requirements for this software update (this info is accessible through pressing: MENU-STATUS->VERSION INFO):

*****DUAL DSP MUST BE INSTALLED TO USE THIS SOFTWARE*****

Release Notes: The software update will provide functionality/ usability improvements to the features and capabilities of this model. These are as follows:

- Audio Return Channel is operational in this release.
- Restricted operation with incompatible PC resolutions.

