

Software Update Notification

You will need a Windows-compatible computer and a (pin to pin) RS-232 cable.

☐ RECOMMEND UPDATING ALL UNITS.

☐ UPDATE UNITS S/N: _____
PLEASE ADVISE CUSTOMERS AND UPDATE UNITS ONLY WHERE APPLICABLE.

☒ NEW FEATURES ADDED IN THIS SOFTWARE RELEASE ARE INTENDED TO IMPROVE OPERATION/PERFORMANCE. UPDATE IS OPTIONAL.

Dependencies and requirements for this software update (this info is accessible through pressing: MENU-STATUS->VERSION INFO):

Release Notes: The software update will provide functionality/ usability improvements to the features and capabilities of this model. These are as follows:

- added new skin colours (now blue, red, green, silver)
- added new feature: any input selection will now wake the unit from standby.
- added new feature: software version info is now available via CAN-Bus.
- added new feature: large volume feature for the rotary knob.

NOTES:

1. Due to the nature of the file size for this update, you may notice that the front and back end software may fail to update. This may result in either a black touchscreen or a message to contact Customer Service. If the unit does not revive after 5 mins. upon completion of the download, you will need to full power cycle the unit a few times to complete the update.
2. This software release is a stage in the CAN Bus launch process. Details relating to the official CAN-Bus launch will shortly be posted on the Classe website www.classeaudio.com. CAN-Bus will not be fully operational before this point.